



Jetstream[®] JetCraft Release Notes

Release 3.3

Document Number 1000-A2-GK42-10
November 2003

Introduction

JetCraft Release 3.3 is a major release to support CPX-1000 Release 3.3.

This release note identifies enhancements and describes known and resolved issues in JetCraft 3.3.

New in JetCraft Release 3.3

JetCraft Release 3.3 supports the following:

- Network Resource Manager
- Voice Quality Alarm
- Filter IAD by Software and Hardware version

Interoperability

CPX-1000 Works with release 3.3 of the CPX-1000.

Platforms JetCraft release 3.3 is supported on Windows 98, Windows NT (Service Pack 5), and Windows 2000 (except Terminal Server). JetCraft is not supported on Windows 95, ME, or XP.

Installation Note

When installing JetCraft on Windows 98:

1. After you have loaded JetCraft, right click on the JetCraft icon to select the memory tab.
2. Enter the following values:

Description	Workaround
Initial Environment	32768
MS-DOS	32768
Extended Memory	32768

Helpful Hints

The "tree-view displays an X mark on an object to represent an alarm occurrence (not the lock/unlock state of the object).

Release Considerations

IAD Manager – LES IADs

The standard LES does not support the concept of delayed IAD restart. When using Jetvision with LES IADs, all restarts will be forced.

LES EOC does not support IAD software version and serial number in the MIB. Therefore, LES IADs may not display IAD hardware model, software version, or serial number correctly in IAD Manager.

Known Issues in Release 3.3

Description	Workaround
JetCraft may hang when there are a large number of active alarms and Alarm Polling is set to 3-4 seconds	Reset Alarm polling to a longer interval.
While in graphical mode and displaying multiple parameters, if two or more parameters with very different ranges are selected for display (on the same y-axis), parameters with smaller values may not be visible.	Select one parameter at a time to display graphically, display parameters with similar ranges, or use tabular representation to view parameters.
Card shelf alarms may not be displayed properly (with yellow or red highlight) while in <i>Shelf view</i> of JetCraft.	Use JetVision for proper alarm display.
The ISDN IAD modify window needs to be resized to display the D-Channel tab information.	Resize the window.

Issues Resolved in Release 3.3

Description	Resolution
If connection between the CPX and JetCraft is lost, JetCraft hangs for several minutes.	JetCraft changed to timeout in less than two minutes if connection is lost to CPX.
EC or ECAC Card removal does not raise an alarm.	Alarm raised.

Warranty, Sales, Service, and Training Information

Contact your local sales representative, service representative, or distributor directly for any help needed. For additional information concerning warranty, sales, service, repair, installation, documentation, training, distributor locations, or Paradyne worldwide office locations, use one of the following methods:

- Internet: Visit the Paradyne World Wide Web site at www.paradyne.com. (Be sure to register your warranty at www.paradyne.com/warranty.)
- Telephone: Call our automated system to receive current information by fax or to speak with a company representative.
 - Within the U.S.A., call 1-800-870-2221
 - Outside the U.S.A., call 1-727-530-2340