



# Jetstream<sup>®</sup> JetCraft Release Notes

## Release 2.5

Document Number 1000-A2-GK44-00

February 2003

---

## Introduction

JetCraft Release 2.5 is a major release to support CPX-1000 Release 2.5.

This release note identifies enhancements and describes known and resolved issues in JetCraft 2.5.

## New in JetCraft Release 2.5

JetCraft Release 2.5 supports the following:

- 12-Port T1 Card
- STS1 PSTN interface with integrated compression
- Up to 4000 IADs
- Network Resource Manager
- Voice Quality Alarm
- Remote IAD Restart
- IAD Software Version in IAD Manager
- Filter IAD by Software Version
- Selected JetStat functionality, including PG and IG link (requires manual refresh)
- Configurable Parameters: ATM Automatic Path Switching Configuration (APS), CDV (Cell Delay Variation), and Line Build Out (LBO) on per interface basis
- Dynamic Compression
- Line Card Reboot Command
- Real Time Monitoring for CP Card
- New IAD Creation Wizard

## Interoperability

**CPX-1000** Works with release 2.5 of the CPX-1000.

**Platforms** JetCraft release 2.5 is supported on Windows 98, Windows NT (Service Pack 5), and Windows 2000 (except Terminal Server). JetCraft is not supported on Windows 95, ME, or XP.).

## Known Issues in Release 2.5

Description	Workaround
While in graphical mode and displaying multiple parameters, if two or more parameters with very different ranges are selected for display (on the same y-axis), parameters with smaller values may not be visible.	Select one parameter at a time to display graphically, display parameters with similar ranges, or use tabular representation to view parameters.
Card shelf alarms may not be displayed properly (with yellow or red highlight) while in <i>Shelf view</i> of JetCraft.	Use JetVision for proper alarm display.

## Issues Resolved in Release 2.5

Description	Resolution
If connection between the CPX and JetCraft is lost, JetCraft hangs for several minutes.	JetCraft changed to timeout in less than two minutes if connection is lost to CPX.
JetCraft and JetVision do not display serial numbers for all cards.	Updated to reflect serial numbers for all cards.
EC or ECAC Card removal does not raise an alarm.	Alarm raised.
JetCraft and JetVision do not show T1 transition card not found.	Alarm is raised if T1 transition card is not found.

## Warranty, Sales, Service, and Training Information

Contact your local sales representative, service representative, or distributor directly for any help needed. For additional information concerning warranty, sales, service, repair, installation, documentation, training, distributor locations, or Paradyne worldwide office locations, use one of the following methods:

- **Internet:** Visit the Paradyne World Wide Web site at [www.paradyne.com](http://www.paradyne.com). (Be sure to register your warranty at [www.paradyne.com/warranty](http://www.paradyne.com/warranty).)
- **Telephone:** Call our automated system to receive current information by fax or to speak with a company representative.
  - Within the U.S.A., call 1-800-870-2221
  - Outside the U.S.A., call 1-727-530-2340