


## HotWire 7915 E1 SDSL Standalone Termination Unit Erratum

Document Number 7915-A2-GK40-00

September 1997

The first HotWire 7915 E1 SDSL Standalone Termination Units have an invalid label on the back panel. The connector labeled **DS1** is actually a **120-Ohm E1** interface. The correct labeling is shown below.



97-15704

### G.703-Compatible (120-Ohm Interface) HotWire 7915 – Rear Panel



\*7915-A2-GK40-00\*