

WARNING

PLEASE READ THESE INSTALLATION INSTRUCTIONS

Please ensure that the Ethernet interface to the MCC Plus card (Part No. 8000-B1-100 or 8000-B1-101) is cabled into Port 19 of the Hotwire® 8800/8810 DSLAM chassis. If you are replacing an MCC card with an MCC Plus card, move the Ethernet interface cable to the Slot 19 RJ48 connector.

