

## Jetstream® JetCraft Release Notes

### Release 3.2

Document Number 1000-A2-GK42-00  
September 2002

---

## Introduction

Release 3.2 is a major release of JetCraft to support CPX-1000.

This release note describes new or changed functionality in JetCraft, identifies closed issues, and provides information on open issues.

## New Features

JetCraft Release 3.2 supports the following:

- 12 port E1 PSTN interface with integrated compression.
- Dynamic Echo Cancellation and Compression for POTs and ISDN.
- Restart IAD button feature
- E1 Line Status Monitoring
- IAD Port Status Monitoring
- Directory field added as searchable field for IAD filtering

## Components

Component	Part Number
JetCraft Software 3.2	1000-D1-008

## Interoperability

### CPX-1000

Works with release 3.2 of the CPX-1000.

### Platforms

JetCraft release 3.2 is supported on Windows 98, Windows NT (Service Pack 5) and Windows 2000 (except Terminal Server).

### Installation Note

When installing JetCraft on Windows 98:

1. After you have loaded JetCraft, right click on the JetCraft icon to select the memory tab.
2. Enter the following values:

Field	Value
Initial Environment	32768
MS-DOS	32768
Extended Memory	32768

## Helpful Hints

The “tree view” displays an X mark on an object to represent an alarm occurrence (not the lock/unlock state of the object).

## Known Issues

Description	Workaround
JetCraft may hang when there are a large number of active alarms and Alarm Polling is set to 3-4 seconds.	Reset Alarm polling to a longer interval.
While in graphical mode and displaying multiple parameters, if two (or more) parameters with very different ranges are selected for display (on the same y-axis), the parameter(s) with smaller values may not be visible.	Select one parameter at a time to display graphically, display parameters with similar ranges, or use tabular representation to view parameters

## Resolved Issues

Description	Status
JetCraft/JetVision: Network PG members operational state is not displayed visually if port is disabled.	Resolved.
JetCraft displays incorrect error messages when invalid channel is entered during V5.2 interface group creation.	Resolved.
Card shelf alarms may not display properly (with yellow or red highlight) while in <i>Shelf</i> view of JetCraft.	Resolved.
The Re-Login window does not appear if Re-Login is selected. This occurs in Windows 2000 and Windows NT.	Resolved.

## Warranty, Sales, Service, and Training Information

Contact your local sales representative, service representative, or distributor directly for any help needed. For additional information concerning warranty, sales, service, repair, installation, documentation, training, distributor locations, or Paradyne worldwide office locations, use one of the following methods:

- **Internet:** Visit the Paradyne World Wide Web site at [www.paradyne.com](http://www.paradyne.com). (Be sure to register your warranty at [www.paradyne.com/warranty](http://www.paradyne.com/warranty).)
- **Telephone:** Call our automated system to receive current information by fax or to speak with a company representative.
  - Within the U.S.A., call 1-800-870-2221
  - Outside the U.S.A., call 1-727-530-2340